

6	5	4	3	2	1
7	8	9	10	11	12
13	17	16	15	14	13
19	20	21	22	23	24
30	29	28	27	26	25
31	32	33	34	35	36

Land Ownership _____

6	5	4	3	2	1	
7	8	9	10	11	12	
13	17	16	15	14	13	
18	20	21	22	23	24	
29	29	28	27	26	25	
31	32	33	34	35	36	

Land Ownership _____

6	5	4	3	2	1
7	8	9	10	11	12
18	17	16	15	USA	13
19	20	21	22	23	24
30	29	28	27	26	25
31	32	33	34	35	36

Land Ownership.....

F-1-A

SEND BOOK

County PRAIRIE

T. 15N. R. 45E Plat No. 6

Farm Checked: Date 5-15-69

MONTANA WATER RESOURCES BOARD
Water Resources Survey

Photo No. 14TT-92, 44TT-235

By JIM REHBEIN

£ 237

Legal Land Owner JAMES C., LLOYD C., JACK & ROBERT P. Mc MULLIN

Address BROCKWAY, MONTANA

Operator SAME

Address SAME

Water is delivered by:— 1. Private System; 2. Ditch Company; 3. State Project; 4. Federal Project; 5. Irrigation District

App. No. Decree No.	NAME OF APPROPRIATOR TO WHOM DECREED	NAME OF STREAM	Date App. Date Priority	Miner's Inches	In Use	NAME OF DITCH (Water Delivered By)	No.	R/F	Present Irr. Acres	Irrigable Acres
* 1-371-A	LLOYD C. Mc MULLIN ETAL	A TRIB OF TIMBER CR.	1962	800	YES	McMULLIN DAM, DITCH, DIKES	1	R	57	0
** 1-343	EMIL SCHUNKER	TIMBER CREEK	5-18-1940	200	YES	SCHUNKER & Mc MULLIN DAMS & DIKES	1	F	69	31
* 1-371	LLOYD C. Mc MULLIN	A TRIB OF TIMBER CR.	1960	1000	YES	McMULLIN DAM, DIKES	1	R	20	0

NOTE: R—Denotes Regular Irrigation. F—Flood Irrigation.

Adequate Supply: Yes..... No..... Explain.....

Remarks
* THIS APPROPRIATION ALSO COVERED NENE, SEC. 15, USA LAND, LEASED BUT NEVER USED. BLM LAND - THEY WILL NOT HELP ON COST OF CLEARING OR LEVELING - SO NO PX EITHER

** SCHUNKER PUT MOST OF THIS SYSTEM IN, BUT Mc MULLINS HAVE IMPROVED IT SOME. THEY ALSO FILLED IN AND LEVELLED THE CREEK IN SOME PLACES. ALL WASHED OUT DIKES ON PHOTO # 14TT-92. WILL BE REPAIRED THIS SUMMER.

Mc MULLINS HAVE 4 LARGE DAMS THEY USE FOR FLOOD CONTROL & IRRIGATION. THEY CAN IRRIGATE WHEN THEY WANT TO. THEY HAVE REMOVED THE BRUSH & TREES ON TIMBER CREEK A.F. & LEVELLED THE CREEK BED & SEDED IT TO HAY IN N^o 24, ALSO IN PLACES IN S^o 24, SEC. 10. THEY HAVE CLEARED THE BRUSH AND TREES FROM S.F. BUT HAVE NOT LEVELLED IT YET. THEY DO NOT HAVE A DAM ON S.F., SO DO NOT IRRIGATE THAT. PX IN N^o 24, SEC. 24 COULD BE IRRIGATED WITH A DAM OR TWO WORK - BRUSH NOT CLEARED. THEY HAVE THEIR OWN CUT & SLOPPER - River Basin MISSOURI!

Also in: Plat No. 7 Twp. 15N. Rge. 46E | Plat No. 13 Twp. 14N. Rge. 46E | Plat No. Twp. Rge.
 Plat No. 12 Twp. 14N. Rge. 45E | Plat No. Twp. Rge. | Plat No. Twp. Rge.
 Information From: LLOYD & ROBERT Mc MULLIN