


Information From:
F. J. Bywater



7-A. 8-B

F-1-A
County Missoula

Farm Checked: Date.....7-21-59

By Vaughn Chadbourne

Legal Land Owner D. C. & Eva Casper

Operator

Water is delivered by:— 1. Private System; 2. Ditch Company; 3. State Project; 4. Federal Project; 5. Irrigation District;

If under Ditch Company, Irrigation District, or Government Project, state the number of shares or inches, acre feet, as the case may be in said system

[illegible]

NOTE: R—Denotes Regular Irrigation. F—Flood Irrigation. P—Water diverted by means of pumping. G—Water diverted by gravity. S—Stored Water.

Condition of System	Topography	River Basin	Columbia River
1. The system is in good condition. 2. The system is in fair condition. 3. The system is in poor condition. 4. The system is in very poor condition.	1. The topography is flat. 2. The topography is hilly. 3. The topography is mountainous. 4. The topography is very mountainous.	1. The river basin is small. 2. The river basin is medium. 3. The river basin is large. 4. The river basin is very large.	1. The Columbia River is short. 2. The Columbia River is medium. 3. The Columbia River is long. 4. The Columbia River is very long.

Adequate Supply: Yes..... No..... Explain.....

Remarks

Also in: Plat No. <u>67</u> Twp. <u>13N</u> Rge. <u>10W</u>	Plat No. Twp. Rge.	Plat No. Twp. Rge.
Plat No. <u>68</u> Twp. <u>14N</u> Rge. <u>11W</u>	Plat No. Twp. Rge.	Plat No. Twp. Rge.

Information From:
Leonard Sandstrom

F-1-A
Missoula
County

Farm Checked: Date 7-22-59

By Vaughn Chadbourne

STATE OF MONTANA
STATE ENGINEERS OFFICE
Water Resources Survey

T. 14N R. 22W Plat No. 44

Photo No. 1P-73

Legal Land Owner Rueben Le Baron Address

Operator	Game	Address
1	1	1
2	2	2
3	3	3
4	4	4
5	5	5
6	6	6
7	7	7
8	8	8
9	9	9
10	10	10
11	11	11
12	12	12
13	13	13
14	14	14
15	15	15
16	16	16
17	17	17
18	18	18
19	19	19
20	20	20
21	21	21
22	22	22
23	23	23
24	24	24
25	25	25
26	26	26
27	27	27
28	28	28
29	29	29
30	30	30
31	31	31
32	32	32
33	33	33
34	34	34
35	35	35
36	36	36
37	37	37
38	38	38
39	39	39
40	40	40
41	41	41
42	42	42
43	43	43
44	44	44
45	45	45
46	46	46
47	47	47
48	48	48
49	49	49
50	50	50
51	51	51
52	52	52
53	53	53
54	54	54
55	55	55
56	56	56
57	57	57
58	58	58
59	59	59
60	60	60
61	61	61
62	62	62
63	63	63
64	64	64
65	65	65
66	66	66
67	67	67
68	68	68
69	69	69
70	70	70
71	71	71
72	72	72
73	73	73
74	74	74
75	75	75
76	76	76
77	77	77
78	78	78
79	79	79
80	80	80
81	81	81
82	82	82
83	83	83
84	84	84
85	85	85
86	86	86
87	87	87
88	88	88
89	89	89
90	90	90
91	91	91
92	92	92
93	93	93
94	94	94
95	95	95
96	96	96
97	97	97
98	98	98
99	99	99
100	100	100

Water is delivered by:—* 1. Private System; 2. Ditch Company; 3. State Project; 4. Federal Project; 5. Irrigation District

If under Ditch Company, Irrigation District, or Government Project, state the number of shares or inches, acre feet, as the case may be in said system

[illegible]

NOTE: R—Denotes Regular Irrigation. F—Flood Irrigation, P—Water diverted by means of pumping, G—Water diverted by gravity, S—Stored Water.


Condition of System	Topography	River	Easin	Columbia River

Adequate Supply:		Yes	No	Explain
1	2	3	4	5
6	7	8	9	10
11	12	13	14	15
16	17	18	19	20
21	22	23	24	25
26	27	28	29	30
31	32	33	34	35
36	37	38	39	40
41	42	43	44	45
46	47	48	49	50
51	52	53	54	55
56	57	58	59	60
61	62	63	64	65
66	67	68	69	70
71	72	73	74	75
76	77	78	79	80
81	82	83	84	85
86	87	88	89	90
91	92	93	94	95
96	97	98	99	100

Remarks Peiben Le Baron says that the ditch for A-1552 was never completed & used.

Also in: Plat No..... Twp..... Rge..... Plat No..... Twp..... Rge..... Plat No..... Twp..... Rge.....
Plat No..... Twp..... Rge..... Plat No..... Twp..... Rge..... Plat No..... Twp..... Rge.....

Information From:
Rueben Le Baron



8-5

County Missoula

Farm Checked: Date.....7-15-59.....

By Vaughn Chadbourne

STATE OF MONTANA
STATE ENGINEERS OFFICE
Water Resources Survey

T. 14N R. 22W Plat. No. 44

Photo No. 1P-73; 1P-74

Legal Land Owner Leonard & Joyce B. Sandstrom

Address

Operator Leonard Sandstrom

Address

Water is delivered by: ☒ 1. Private System; ☐ 2. Ditch Company; ☐ 3. State Project; ☐ 4. Federal Project; ☐ 5. Irrigation District

If under Ditch Company, Irrigation District, or Government Project, state the number of shares or inches, acre feet, as the case may be in said system

[illegible]

NOTE: R—Denotes Regular Irrigation. F—Flood Irrigation. P—Water diverted by means of pumping. G—Water diverted by gravity. S—Stored Water.


Condition of System Topography River Basin Columbia River

Adequate Supply: Yes ☒ No ☐ Explain _____

Remarks: A-1563 was not appropriated for this land, but is now being used here. Sandstrom says that the ditch now being used was dug in 1956 & diverts from Tank Creek at a much higher place than did the original ditch.

Also in	Plot No. <u>34</u>	Twp. <u>15N</u>	Rge. <u>23W</u>	Plot No.	Twp.	Rge.	Plot No.	Twp.	Rge.
	Plot No.	Twp.	Rge.	Plot No.	Twp.	Rge.	Plot No.	Twp.	Rge.

Information From:
Leonard Sandstrom



5=A, 6=A

By Vaughn Chadbourne

STATE OF LOUISIANA
STATE ENGINEERS OFFICE
Water Resources Survey

T^{14N} R^{22W} Plat No. 44
Photo No. 1P-73

Legal Land Owner F. J. & Alice Burton Bywater Address

Operator Same Address

Water is delivered by:— ^x 1. Private System; 2. Ditch Company; 3. State Project; 4. Federal Project; 5. Irrigation District

If under Ditch Company, Irrigation District, or Government Project, state the number of shares or inches, acre feet, as the case may be in said system

[illegible]

NOTE: R—Denotes Regular Irrigation. F—Flood Irrigation. P—Water diverted by means of pumping. G—Water diverted by gravity. S—Stored Water.

Condition of System	Topography	River Basin	Columbia River
---------------------	------------	-------------	----------------


Adequate Supply: Yes..... No..... Explain

Remarks Bywater says that he used to sprinkle irrigate his bottom land, but he quit because when the river was low his pump couldn't reach the water. He is now attempting to have Montana Power Co. extend their power line to where he can again pump from the river.

Also in: Plat No.....	Twp.....	Rge.....	Plat No.....	Twp.....	Rge.....	Plat No.....	Twp.....	Rge.....
Plat No.....	Twp.....	Rge.....	Plat No.....	Twp.....	Rge.....	Plat No.....	Twp.....	Rge.....

Information From:

F. J. Bywater



7-A, 8-B

County Missoula

Farm Checked: Dc'a.....7-21-59

By Vaughn Chadbourne

STATE OF MONTANA
STATE ENGINEERS OFFICE
Water Resources Survey

T. 14N R. 22W Plat No. 44

Photo No. ?

Legal Land Owner D. C. & Eva Casper Address _____

Operator	Address
----------------	---------------

Water is delivered by:— 1. Private System; 2. Ditch Company; 3. State Project; 4. Federal Project; 5. Irrigation District

If under Ditch Company, Irrigation District, or Government Project, state the number of shares or inches, acre feet, as the case may be in said system

[illegible]

NOTE: R—Denotes Regular Irrigation. F—Flood Irrigation. P—Water diverted by means of pumping. G—Water diverted by gravity. S—Stored Water.

Condition of System	Topography	River Basin	Columbia River
---------------------	------------	-------------	----------------

Adequate Supply: Yes..... No..... Explain

Remarks	
---------	--

.....

Information From:

Also in:	Plat No.....	Twp.....	Rge.....	Plat No.....	Twp.....	Rge.....	Plat No.....	Twp.....	Rge.....	Plat No.....	Twp.....	Rge.....
----------	--------------	----------	----------	--------------	----------	----------	--------------	----------	----------	--------------	----------	----------

Plat No.	Twp.	Rge.	Plat No.	Twp.	Rge.	Plat No.	Twp.	Rge.	Leonard Sandstrom
---------------	-----------	-----------	---------------	-----------	-----------	---------------	-----------	-----------	-------------------

Information From:

Leonard Sandstrom

6	5	4	3	2	1
7	8	9	10	11	12
13	14	15	16	17	18
19	20	21	22	23	24
25	26	27	28	29	30
B	31	32	33	34	35

31-B

P-1-A
County Missoula

Farm Checked: Date 7-22-59

By Vaughn Chadbourne

STATE OF MONTANA
STATE ENGINEERS OFFICE
Water Resources Survey



T. 14N R. 22W Plat No. 44

Photo No. 1P-73

Legal Land OwnerRueben Le Baron..... Address

Operator	Same	Address

Water is delivered by:—^x 1. Private System; 2. Ditch Company; 3. State Project; 4. Federal Project; 5. Irrigation District

If under Ditch Company, Irrigation District, or Government Project, state the number of shares or inches, acre feet, as the case may be in said system

[illegible]

NOTE: R—Denotes Regular Irrigation. F—Flood Irrigation. P—Water diverted by means of pumping. G—Water diverted by gravity. S—Stored Water.

Condition of System	Topography	River Basin	Columbia River
---------------------------	------------------	-------------------	----------------


Adequate Supply: Yes..... No..... Explain

Remarks Reuben Le Baron says that the ditch for A-1552 was never completed & used.

Also in: Plat No..... Twp..... Rge.....	Plat No..... Twp..... Rge.....	Plat No..... Twp..... Rge.....
Plat No..... Twp..... Rge.....	Plat No..... Twp..... Rge.....	Plat No..... Twp..... Rge.....

Information From:

Dueben Le Baron



8-C

County Missoula

Farm Checked: Date 7-15-59

By Vaughn Chadbourne.....

STATE OF MONTANA
STATE ENGINEERS OFFICE
Water Resources Survey

T. 14N R. 22W Plat No. 44

Photo No. 1P-73; 1P-74

Legal Land Owner Leonard E. Joyce R. Sandsstrom Address

Operator Leonard Sandstrom Address

Water is delivered by:—^x 1. Private System; 2. Ditch Company; 3. State Project; 4. Federal Project; 5. Irrigation District

If under Ditch Company, Irrigation District, or Government Project, state the number of shares or inches, acre feet, as the case may be in said system

[illegible]

NOTE: R—Denotes Regular Irrigation. F—Flood Irrigation. P—Water diverted by means of pumping. G—Water diverted by gravity. S—Stored Water.


Condition of System	Topography	River Basin	Columbia River
---------------------------	------------------	-------------------	----------------

Adequate Supply: Yes..... No..... Explain
Remarks A-1563 was not appropriated for this land, but is now being used here. Sandstrom says that the ditch now being used was dug in 1956 & diverts from Tank Creek at a much higher place than did the original ditch.

[The page contains faint horizontal lines suggesting ghosting or extremely light printing.]

Also in: Plat No. <u>34</u> Twp. <u>15N</u> Rge. <u>22W</u>	Plat No. Twp. Rge.	Plat No. Twp. Rge.	Information From: Leonard Sandstrom
Plat No. Twp. Rge.	Plat No. Twp. Rge.	Plat No. Twp. Rge.	

Information From:
Leonard Sandstrom



5-A, 8-A