

County Missoula

Farm Checked: Date.....9-9-59

By George Tate

Legal Land Owner Martha S. Anderson

Operator Same

Water is delivered by: 1. Private System; 2. Ditch Company; 3. State Project; 4. Federal Project; 5. Irrigation District

If under Ditch Company, Irrigation District, or Government Project, state the number of shares or inches, acre feet, as the case may be in said system

[illegible]

NOTE: R—Denotes Regular Irrigation. F—Flood Irrigation. P—Water diverted by means of pumping. G—Water diverted by gravity. S—Stored Water.


Condition of System	Topography	River Basin	Columbia River
1. <u>Condition of System</u> 2. <u>Topography</u> 3. <u>River Basin</u> 4. <u>Columbia River</u>	1. <u>Condition of System</u> 2. <u>Topography</u> 3. <u>River Basin</u> 4. <u>Columbia River</u>	1. <u>Condition of System</u> 2. <u>Topography</u> 3. <u>River Basin</u> 4. <u>Columbia River</u>	1. <u>Condition of System</u> 2. <u>Topography</u> 3. <u>River Basin</u> 4. <u>Columbia River</u>

Adequate Supply: Yes ☒ No ☐ Explain _____

Remarks

Also in: Plat No.	Twp.	Rge.	Plat No.	Twp.	Rge.	Plat No.	Twp.	Rge.
Plat No.	Twp.	Rge.	Plat No.	Twp.	Rge.	Plat No.	Twp.	Rge.

Information From:
Mrs. Bakke



14C

County:

Farm Checked: Date 9-9-59

By George Tate

STATE ENGINEERS OFFICE

Water Resources Survey

Photo No. 861; 862

Legal Land Owner Edward Beck

AddressCandor.....

Operator Same

Address

Water is delivered by:— 1. Private System; 2. Ditch Company; 3. State Project; 4. Federal Project; 5. Irrigation District

If under Ditch Company, Irrigation District, or Government Project, state the number of shares or inches, acre feet, as the case may be in said system

[illegible]

NOTE: R—Denotes Regular Irrigation. F—Flood Irrigation. P—Water diverted by means of pumping. G—Water diverted by gravity. S—Stored Water.

Condition of System _____ Topography _____ River Basin _____ Columbia River _____


Adequate Supply: Yes..... No..... Explain.....

Remarks

Also in: Plat No..... Twp..... Rge.....	Plat No..... Twp..... Rge.....	Plat No..... Twp..... Rge.....
Plat No..... Twp..... Rge.....	Plat No..... Twp..... Rge.....	Plat No..... Twp..... Rge.....

Information From:


Mrs. Bakke




10-D, 11-B

10-D, 11-B

Art Hall



10-E, 14-B



12-B. 26-A

F-1-A
County Missoula

Farm Checked: Date 9-9-59

By George Tate

Legal Land Owner Lloyd E. Maske

Operator Same

Water is delivered by:— 1. Private System; 2. Ditch Company; 3. State Project; 4. Federal Project; 5. Irrigation District

If under Ditch Company, Irrigation District, or Government Project state the number of shares or inches, acre feet, as the case may be in said system

[illegible]

NOTE: R—Denotes Regular Irrigation. F—Flood Irrigation. P—Water diverted by means of pumping. G—Water diverted by gravity. S—Stored Water.

Condition of System Topography River Basin Columbia River

Adequate Supply: Yes..... No..... Explain.....

Remarks


Also in: Plat No.....	Twp.....	Rge.....	Plat No.....	Twp.....	Rge.....	Plat No.....	Twp.....	Rge.....
Plat No.....	Twp.....	Rge.....	Plat No.....	Twp.....	Rge.....	Plat No.....	Twp.....	Rge.....

Information From:

Mr̃s. Bakkē

Plat No. 2

District

[illegible]

24-D

F-1-A
County Missoula

Farm Checked: Date 9-9-59

By George Tate

Legal Land Owner Robert H. & Gladys W. Monrod Newman

Operator

Water is delivered by:— 1. Private System;

2. Ditch Company;

3. State Project;

4. Federal Project:

5. Irrigation District

If under Ditch Company, Irrigation District, or Government Project, state the number of shares or inches, acre feet, as the case may be in said system

[illegible]

NOTE: R—Denotes Regular Irrigation. F—Flood Irrigation. P—Water diverted by means of pumping. G—Water diverted by gravity. S—Stored Water.

Condition of System	Topography	River Basin	Columbia
1. The system is in good condition and is operating at a high level of efficiency. 2. The system is in fair condition and is operating at a moderate level of efficiency. 3. The system is in poor condition and is operating at a low level of efficiency. 4. The system is in very poor condition and is operating at a very low level of efficiency.	1. The topography is flat and the system is operating at a high level of efficiency. 2. The topography is hilly and the system is operating at a moderate level of efficiency. 3. The topography is mountainous and the system is operating at a low level of efficiency. 4. The topography is very mountainous and the system is operating at a very low level of efficiency.	1. The river basin is small and the system is operating at a high level of efficiency. 2. The river basin is medium-sized and the system is operating at a moderate level of efficiency. 3. The river basin is large and the system is operating at a low level of efficiency. 4. The river basin is very large and the system is operating at a very low level of efficiency.	1. The Columbia River is in good condition and is operating at a high level of efficiency. 2. The Columbia River is in fair condition and is operating at a moderate level of efficiency. 3. The Columbia River is in poor condition and is operating at a low level of efficiency. 4. The Columbia River is in very poor condition and is operating at a very low level of efficiency.

Adequate Supply: Yes..... No..... Explain.....

Remarks

Also in: Plat No. 6 Twp. 20N Rge. 17W
Plat No. Twp. Rge.

Plat No.	Twp.	Rge.
Plat No.	Twp.	Rge.

Plat No.	Twp.	Rge.
Plat No.	Twp.	Rge.

Information From:

Mrs. Bakke

Plat No.....2

4


7 District

[illegible]

OK

from:

e



36-D

County Missoula

Farm Checked: Date.....9-9-59

By George Tate

T. 21N R. 17W Plat No. 2

Photo No. 862

Legal Land Owner Martha S. Anderson Address Condon

Operator	Same	Address

Water is delivered by:— 1. Private System; 2. Ditch Company; 3. State Project; 4. Federal Project; 5. Irrigation District

If under Ditch Company, Irrigation District, or Government Project, state the number of shares or inches, acre feet, as the case may be in said system

NOTE: R—Denotes Regular Irrigation. F—Flood Irrigation. P—Water diverted by means of pumping. G—Water diverted by gravity. S—Stored Water.

Condition of System	Topography	River Basin	Columbia River
---------------------------	------------------	-------------------	----------------


Adequate Supply:		Yes.....	No.....	Explain
1. Addition				
2. Reduction				
3. Other				

Remarks	
---------	--

Also in: Plat No. Twp. Rge.	Plat No. Twp. Rge.	Plat No. Twp. Rge.
Plat No. Twp. Rge.	Plat No. Twp. Rge.	Plat No. Twp. Rge.

Information From:

Mrs. Bakke



14-0

F-1-A Missoula
County

Farm Checked: Date.....9-9-59

By George Tate

STATE OF MONTANA
STATE ENGINEERS OFFICE
Water Resources Survey

T. 21 R. 17W. Plat No. 2

Photo No. 861; 862

Legal Land Owner Edward Beck Address Candon

Operator	Same	A-Address

Water is delivered by:— 1. Private System; 2. Ditch Company; 3. State Project; 4. Federal Project; 5. Irrigation District

If under Ditch Company, Irrigation District, or Government Project, state the number of shares or inches, acre feet, as the case may be in said system

[illegible]

NOTE: R—Denotes Regular Irrigation. F—Flood Irrigation. P—Water diverted by means of pumping. G—Water diverted by gravity. S—Stored Water.

Condition of System	Topography	River Basin	Columbia River
---------------------------	------------------	-------------------	----------------------


Adequate Supply: Yes..... No..... Explain

Remarks _____

Also in: Plat No..... Twp..... Rge.....	Plat No..... Twp..... Rge.....	Plat No..... Twp..... Rge.....
Plat No..... Twp..... Rge.....	Plat No..... Twp..... Rge.....	Plat No..... Twp..... Rge.....

Information From:

Mrs. Bakke



10-D, 11-B

If under Ditch Company, Irrigation District, c

Photo No. 862; 861

Address

Water is delivered by:— 1. Private System; 2. Ditch Company; 3. State Project; 4. Federal Project; 5. Irrigation District

If under Ditch Company, Irrigation District, or Government Project, state the number of shares or inches, acre feet, as the case may be in said system

[illegible]

NOTE: R—Denotes Regular Irrigation. F—Flood Irrigation. P—Water diverted by means of pumping. G—Water diverted by gravity. S—Stored Water.

Condition of System Topography Valley River Basin Columbia River


Adequate Supply: Yes..... No..... Explain.....

Remarks They do not irrigate at present time. There is no ditch at present time. They are selling place to a new man who intends someday to put in ditch & irrigate. Has no idea where ditch will be. The land in Section 14 is all sub-irrigated.

Also in: Plat No..... Twp..... Rge.....	Plat No..... Twp..... Rge.....	Plat No..... Twp..... Rge.....
Plat No..... Twp..... Rge.....	Plat No..... Twp..... Rge.....	Plat No..... Twp..... Rge.....

Information From:

Art Hall



10-E, 14-B

County Missoula

Farm Checked: Date 9-9-59

By George Tate

STATE OF MONTANA
STATE ENGINEERS OFFICE
Water Resources Survey

T. 21N R. 17W Plat No. 2

Photo No. 863

Legal Land Owner Hamilton Doreen & Millie Katherine Hill Address Condon

Operator	Name	Address

Water is delivered by: - 1. Private System; 2. Ditch Company; 3. State Project; 4. Federal Project; 5. Irrigation District

If under Ditch Company, Irrigation District, or Government Project, state the number of shares or inches, acre feet, as the case may be in said system

NOTE: R—Denotes Regular Irrigation. F—Flood Irrigation. P—Water diverted by means of pumping. G—Water diverted by gravity. S—Stored Water.

Condition of System	Topography	River Basin	Columbia River
---------------------------	------------------	-------------------	----------------------


Adequate Supply:	Yes	No	Explain

Remarks

Also in: Plat No. <u>6</u> Twp. <u>20N</u> Rge. <u>17W</u>	Plat No. Twp. Rge.	Plat No. Twp. Rge.
Plat No. Twp. Rge.	Plat No. Twp. Rge.	Plat No. Twp. Rge.

Information From:

Mrs. Bakke



12-B, 26-A

Mrs. Bakke

6	5	4	3	2	1
7	8	9	10	11	12
18	17	16	15	14	13
19	20	21	22	23	24
30	29	28	27	26	25
31	32	33	34	35	36

b

24-D

F-1-A
County Missoula

Farm Checked: Date 2-9-59

By George Tate

STATE OF MONTANA
STATE ENGINEERS OFFICE
Water Resources Survey

T. 21N R. 17W Plat No. 2

Photo No. 1044

Legal Land Owner Robert H. & Gladys W. Monrod Newman Address Condon

[illegible]

Water is delivered by:— 1. Private System; 2. Ditch Company; 3. State Project; 4. Federal Project; 5. Irrigation District

If under Ditch Company, Irrigation District, or Government Project, state the number of shares or inches, acre feet, as the case may be in said system

[illegible]

NOTE: R—Denotes Regular Irrigation. F—Flood Irrigation. P—Water diverted by means of pumping. G—Water diverted by gravity. S—Stored Water.

Condition of System Topography River Basin Columbia

Adequate Supply: Yes..... No..... Explain

Remarks	
---------	--

.....

.....

.....

.....

.....

.....

.....

.....

Address	Plot No.	East	20N	Page	177	Plot No.	East	Page	Plot No.	East	Page	Information From:
---------	----------	------	-----	------	-----	----------	------	------	----------	------	------	-------------------


Also in:	Plot No.	Twp.	Rge.	Plot No.	Twp.	Rge.	Plot No.	Twp.	Rge.	Mrs. Bakke
----------	----------	------	------	----------	------	------	----------	------	------	------------

1st NO.	2nd NO.	3rd NO.	4th NO.	5th NO.	6th NO.	7th NO.	8th NO.	9th NO.	10th NO.	11th NO.	12th NO.	13th NO.	14th NO.	15th NO.	16th NO.	17th NO.	18th NO.	19th NO.	20th NO.	21st NO.	22nd NO.	23rd NO.	24th NO.	25th NO.	26th NO.	27th NO.	28th NO.	29th NO.	30th NO.	31st NO.	32nd NO.	33rd NO.	34th NO.	35th NO.	36th NO.	37th NO.	38th NO.	39th NO.	40th NO.	41st NO.	42nd NO.	43rd NO.	44th NO.	45th NO.	46th NO.	47th NO.	48th NO.	49th NO.	50th NO.	51st NO.	52nd NO.	53rd NO.	54th NO.	55th NO.	56th NO.	57th NO.	58th NO.	59th NO.	60th NO.	61st NO.	62nd NO.	63rd NO.	64th NO.	65th NO.	66th NO.	67th NO.	68th NO.	69th NO.	70th NO.	71st NO.	72nd NO.	73rd NO.	74th NO.	75th NO.	76th NO.	77th NO.	78th NO.	79th NO.	80th NO.	81st NO.	82nd NO.	83rd NO.	84th NO.	85th NO.	86th NO.	87th NO.	88th NO.	89th NO.	90th NO.	91st NO.	92nd NO.	93rd NO.	94th NO.	95th NO.	96th NO.	97th NO.	98th NO.	99th NO.	100th NO.
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100

information From:

Mrs. Bakke

6	5	4	3	2	1
7	8	9	10	11	12
13	14	15	16	17	18
19	20	21	22	23	24
25	26	27	28	29	30
31	32	33	34	35	36



36-D

.....

.....

.....